

FIG 3 (Related Art)





FIG 4 (Related Art)



○ operating points after optimization

□ operating points, compressor assemblies running at the same rotational speed